
冷氣滴水非儿事。 安善維修不延遲

Water Dripping from Air-conditioners is Not a Small Problem Carry out Proper Repair Without Delay



檢查冷氣機排水管 及排水托盤的堵塞物

Check the drainage pipes and drain trays of air-conditioners for blockage

確保冷氣機膠喉管 妥善及穩固連接 冷氣機底盤及大廈 排水裝置或中央去水管

Make sure that the hoses of air-conditioners are properly and securely connected to the air-conditioner drip trays and then drainage facilities or communal drainage pipe of the building

查詢熱線 Enquiry Hotline: 2868 0000

網站 Website: http://www.fehd.gov.hk

